

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

JAN 10 1995

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) JAN 95 To (mo./yr.) DEC 95
 2. DOGM File Number (Mine No): M /023 /010
 3. Mine Name: NAVAJO SANDSTONE
 4. Mineral(s) Mined (or permitted to mine): SANDSTONE
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
NE 1/4, 1/4, Section 25, Township 13S, Range 2W
1/4, 1/4, Section , Township , Range
1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: ASH GROVE CEMENT CO.
 8. Permanent Street Address : P.O. BOX 51 (25 MILES WEST OF NEPHI)
City, State, Zip: NEPHI UTAH 84648
Phone: (801) 857-1212
 9. Company Representative (or designated operator):
Name: DUANE CRUTCHFIELD
Title: PLANT MANAGER
Business Address: P.O. BOX 51
City, State, Zip: NEPHI, UT 84648
Phone: (801) 857-1212
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☐ No ☒
2. If active, how much ore or mineral was mined? NONE

3. How much additional acreage was disturbed during the past year? NONE
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
- _____
- _____
- _____
5. How much acreage was reclaimed during the past year? APPROX. 8 ACRES
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
- THE EXISTING HIGHWALL WAS BLASTED TO REDUCE SLOPE ANGLE; ADDITIONAL
- STABILIZING DOZER WORK WAS COMPLETED WITH ENTIRE AREA RESEEDED.
- _____
7. What is the total disturbed acreage at years end? _____
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
- COMPLETED; IF RESEEDING IS SUCCESSFUL.
- _____
- _____
- _____

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

DUANE CRUTCHFIELD

Title of Operator:

PLANT MANAGER

Signature of Operator:

Duane Crutchfield

Date:

Jan 25, 1996